T.


STATE OF UTAH

DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340

Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

[.	Gener	al Information ,
	1.	Report Time Period: From (mo./yr.) Aug. 94 To (mo./yr.) Jan 96
	2.	DOGM File Number (Mine No): S / 023/03 /
	3.	Mine Name: BULLSEYE
	4.	Mineral(s) Mined (or permitted to mine): wonder stone"
	5.	Type of mine ☐ Surface Mine or ☐ Underground Mine
	6.	Legal Description (Location of Lands Affected):
		N.W. 1/4, N.E. 1/4, Section 33, Township 14 S, Range 11 W
		1/4,1/4, Section, Township, Range
		1/4,1/4, Section, Township, Range
	7.	Name of Operator or Company: Edwin P. Lister & Roger C. Lister
, "	8.	Permanent Street Address: Po Bot 651 (33 w. 100 S.)
		City, State, Zip: Delta, Utah 84624
		Phone: 801-864-2385
	9.	Company Representative (or designated operator):
		Name: Roger C. Lister
		Title:
		Business Address:
		City, State, Zip: 392 East Main Delta, Ut. 84624
		Phone: 801-864-3452
		Please check if any of the above information has changed since previous year. No
II.	Minin	g and Reclamation
	1.	Was the mine active during the past year? Yes ☑ No ☐
	2.	If active, how much ore or mineral was mined? 50 TONS

	3. How much additional acreage was disturbed during the past year? 1/4 Ac.
	4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
	building Access road & ramp on cast side of Bullcaye Hill
	approx 1000 ft long x 10 ft wide by use of tractor blade
	and ramp was shaped by using existing tailings material (approx 10 to
5.	How much acreage was reclaimed during the past year?
6.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
	Filling back in four trenches that cross-cut a high angle Fault
	Vein - 12 the flaturea southwest of BullsoypHill. Trenches
	were 2 to 3 ft under by 20 ft to 100 ft long and 4 ft deep.
	using a rubber tive tractor bucket. nativegrasses have grown
7.	What is the total disturbed acreage at years end? 2 to 3 acres.
8.	Briefly summarize any mining and/or reclamation plans for the upcoming year.
	Reclaiming an existing Quarry Pit on west side of Bullcaye
	Hill - approx 1/2 acre.
	Renoving approx 50 to 100 Ton of stone material from East
	side with Backhoie - No significant disturbance -mostly digging into the side of the hill near the top less than 1/4 acr
NOTE:	Section III., "Additional Information" applies only to large mining operations.
III. Addition	nal Information
1.	An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2.	Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.
IV. <u>Signatur</u>	re Requirement
I her	eby certify that the foregoing is true and correct.
	Name (Typed or Print): Edwin P. Lister
	Title of Operator:
	Signature of Operator: Date: May: 22 96
	Date: May 22 96

jb